

---

**From:** Jeffrey R Marcell (Generation - 3) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=JEFF136]  
**Sent:** 3/31/2015 5:08:43 PM  
**To:** Michael J Winters (Generation - 34) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=MIC1082]  
**CC:** John Cima (Generation - 34) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=John171]; Jeffrey C Heffelman (Generation - 3) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=Jeffre3]; Kenneth Roller (Services - 6) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=Kenne64]  
**Subject:** RE: Ash Pond ABC inspection 03/31/15  
**Attachments:** 20150331160342587.pdf

Attached.

**Discharge** (seeping) at C Pond, decreasing from previous inspection. Standing water around weir.

Standing water behind sand-bags at 'A' with seeping flow under bags in the entire area. The flow is audible and appears to be coming from under the rip-rap, similar to a "babbling brook". In addition, the southern edge of the 'A' pond interior, from the SE corner to the sandbags, is holding water, something that was not seen last year.

No recent precipitation. Last storm event was 03/26-03/27 and produced roughly 0.7" of rain.

Let me know if you have any questions.

Jeff Marcell

Environmental Supervisor

Possum Point Power Station

Ladysmith & Remington CT Sites

703-441-3813 (phone)

8-795-3813 (tie)

703-441-3897 (fax)